

Immediate Action Required User Safety Notice SN070523

Products:

3M™ Scott™ Air-Pak™ Wireframe, Air-Pak™ 75, Air-Pak™ NxG7 (Upgraded), Air-Pak™ X3 SCBA and Spare Assemblies

Impacted Dates:

May 2021 – February 2023

3M™ Scott™ Air-Pak™ SCBA are safe to use once the instructions in this notice are carried out.

3M™ Scott™ Fire & Safety has received a small number of reports of Air-Pak 75, Air-Pak NxG7 (upgraded), Air-Pak X3 SCBA and spare consoles that were shipped with incorrect programming of the Heads-Up Display (HUD) secondary EoSTI. In the reported cases, although the Vibralert primary EoSTI will alarm at 35% of cylinder pressure in accordance with regulatory requirements, the HUD console lights will only indicate low air (red flashing light as illustrated in **Figure 1**) when the cylinder pressure reaches 25%. While both signals are measuring accurately, the HUD lights for these SCBA editions should be illuminating at 35%.

The following item numbers with consoles manufactured during the date range specified above are impacted:

- Air-Pak Wireframe SCBA configured with the 12th character in the configured item being “1, 2, or 3” (e.g. X3124021000”x”01).
- Air-Pak 75 or NxG7 SCBA configured with the 12th character in the configured item being “1, 2, or 3” (e.g. X3214021000”x”01).
- Air-Pak X3 SCBA configured with the 12th character in the configured item being “1” (e.g. X3314021000”x”01).
- Spare console assemblies 200280-11, -12, -14 (HUD-only consoles for Air-Pak Wireframe, 75, NxG7, or X3).
- Spare console assemblies 200424-11, -12, -14 (PASS consoles for Air-Pak Wireframe, 75, or NxG7).

Red light should flash when
cylinder pressure reaches 35%




Figure 1

The date range for this notice includes SCBA and spare console repair kits manufactured between **May 3, 2021, through February 14, 2023, inclusive**. Please take note of the following actions to determine if any of your SCBA fleet are impacted by this notice and what subsequent actions need to be taken.

Identification and Customer Action

You are receiving this notice because you have been identified by 3M Scott as having purchased from an authorized distributor that may have received SCBA or spare console repair kits falling within the manufacture date range of this Notice. We have asked them to notify you and provide these instructions on how to inspect your fleet to determine if further service actions are necessary.

Refer to **Figure 2** below for labelling examples to help you identify the Mfg. Date of your SCBA console, which will assist in determining whether your SCBA is potentially impacted and requires further inspection.



Figure 2

If you identify one or more consoles within the date range, please remove the SCBA from service and contact your 3M Scott Authorized Service Center (ASC) to complete the repairs required.

We apologize for any inconvenience caused. If you have any additional questions about this Notice please contact your 3M Scott Authorized Service Center, or 3M Scott Technical Support so that a service professional can assist you in completion of the Notice. 3M Scott Technical Support can be contacted at 1-800-247-7257, or scotttechsupport@3m.com, or through the web at www.3M.com/ScottFire.