




# USER SAFETY NOTICE

Dear valued customer,

3M Scott Fire & Safety has received a small number of reports of E-Z Flo+ Mask Mounted Regulators (MMR) that shipped without cover screws installed. We have notified distributors and service centers that were identified as having possibly received incorrect MMR that will, in turn, notify any potentially impacted end users.

Figure 1 identifies the Mask Mounted Regulator (MMR) model that may be impacted by this notice. The affected regulators will have a Part number of 200077-60, -67 Or -68 with a manufacturing date of 08/22/2022.



If after inspection, it is discovered that an MMR is missing the cover screws, take the MMR out of service and contact your 3M Scott Fire & Safety Authorized Service Center to complete the repairs required. If you require additional assistance, you may contact 3M Scott Fire & Safety Technical Support at [scotttechsupport@mmm.com](mailto:scotttechsupport@mmm.com) and reference User Safety Notice SN122022. Refer to Figure 2.

