

March 20, 2008

USER NOTICE

ProSight Safety Eyewear

Model: Driller (part # 77106 to 77111 inclusive)

Dear Customer,

Prosight Distributing Inc. (ProSight Eyewear) is voluntarily removing the **Driller model, (part numbers 77106 to 77111 inclusive, in ALL lens colors)**, distributed between August 1, 2007 and September 30, 2007 from the marketplace. The reason for the removal is a failure to pass yearly testing to CSA Z94.3-02 standards for Safety Spectacles. This item still meets ANSI Z87.1 standards for Protective Spectacles.

Please immediately stop using, selling or distributing the affected product, which was supplied to you by ProSight Distributing Inc. during the period noted above.

To answer questions, or to help determine product possibly affected by this user notice, please contact Prosight Distributing Inc. at (877) 786-3642.

Returns / Refunds

If a Sales Representative from ProSight has not provided you with a refund for this model already, they will complete a credit on site for you within the next six weeks.



ProSight Safety Eyewear
75 Skyline Crescent NE
Calgary, AB T2K 5X2
Phone: 403.516.6600 Toll-Free: 877.786.3642 Fax: 403.275.6973
e-mail: info@prosighteyewear.com web: www.prosighteyewear.com