

## Immediate Action Required



### Products

**3M™ Scott™ Vibralert End-of-Service-Time-Indicator (EoSTI) contained in E-Z Flo+ Mask-Mounted Regulators (MMR)**

**Manufacturing Dates: January 26-29, 2024**



3M Personal Safety Division is issuing a "Stop Use and Action" for the 3M™ Scott™ E-Z Flo+ MMR manufactured between January 26-29, 2024. 3M™ Scott™ E-Z Flo+ MMR are safe to use once the instructions in this notice are carried out.

3M Scott Fire & Safety has been made aware of an E-Z Flo+ MMR having shipped from our factory with a Vibralert EoSTI that failed to function adequately upon initial inspection. The root cause of this failure has been determined, and corrective actions have been undertaken to ensure all shipments after the date range function as designed and approved. There have been no reports of injuries or accidents associated with this notice.

### Instructions for Users

If a 3M Scott respirator or spare parts whose MMR serial number falls within the manufacture/shipment date range of this Notice, you will be contacted by an authorized 3M Scott Authorized Service Center (ASC) or distributor. We have identified specific components and have asked your ASC to notify you to have an inspection performed on your Self-Contained Breathing Apparatus. If you are contacted, please stop use of the identified MMR immediately. If you are not contacted by a 3M Scott ASC or distributor and have questions about this notice, you may contact our Technical Support group at 1-800-247-7257.

### Instructions for Distributors

Upon receipt of this Notice, you will already have received a listing of serial numbers and orders impacted by this Notice, along with instructions on inspection and repair/replacement of affected components. If you have not received a listing, this Notice does not apply to orders we have shipped to you or to your customers. If you still have questions regarding this Notice, please contact 3M Scott Technical Support. Please immediately forward this Notice to any of your customers who have purchased affected products from you and provide any assistance requested by your customers to complete the process.

**If you have any questions or for more information, please contact your local 3M representative or 3M Scott Technical Support.**

We apologize for any inconvenience caused. If you have any additional questions about this Notice please contact your 3M Scott Authorized Service Center, or 3M Scott Technical Support so that a service professional can assist you in completion of the Notice. 3M Scott Technical Support can be contacted at 1-800-247-7257, or [scotttechsupport@3m.com](mailto:scotttechsupport@3m.com), or through the web at [www.3M.com/ScottFire](http://www.3M.com/ScottFire).

#### Personal Safety Division

4320 Goldmine Road  
Monroe, NC 28110

#### In United States of America or Canada

Technical Service 1-800-247-7257  
Customer Service 1-800-247-7257  
[3M.com/ScottFire](http://3M.com/ScottFire)

© 3M 2024. All rights reserved.

3M and Scott are trademarks of 3M Company and its affiliates, used under license in Canada.